



HANDLE WITH CARE

HONEXT® boards must be handled with care to avoid any damage. Due to their low density and surface textures the boards should be moved carefully to prevent scratches.


1. The boards should always be lifted, not dragged along other surfaces.




2. Never let the weight of the board rest on one corner.




3. Store the boards flat to avoid unwanted curvature.



4. Always stack the boards with the A side facing up.





5. Always keep the boards dry and protected from impact druing transport.



WWW.HONEXTMATERIAL.COM NOVEMBER 2022